

## Care and Maintenance of Your SURE-LOC® Sight

Congratulations on selecting a SURE-LOC® sight. Your SURE-LOC® was manufactured using the finest materials and manufacturing techniques available, and requires very little maintenance to keep adjustments crisp and firm. Treat it well, and it will treat you well.

Here are just a few steps to follow to ensure the continued accuracy of your SURE-LOC® sight.

- Keep your sight clean and dry to minimize wear and oxidation. Wipe the entire sight after use to remove dust, dirt, moisture, and oxidizing residue. Use a clean dry cloth paying close attention to the mating contact areas of the mounting block and extension, also the windage block and split-block attachment.
- If your sight gets dirt build-up, use a spray contact cleaner (oil free) to remove the residue.
- If your sight gets wet, simply use a soft cloth to dry it off. When you get the opportunity, use a hair-dryer to remove trapped moisture.
- Store your sight in a clean, dry environment. The padded case it came in is excellent for storage. Wash the foam padding if you see dirt or dust build-up.
- **LIMITED USE OF OIL INSTRUCTIONS:** A small drop of lightweight oil may be used under the adjustment knobs on the ball bearing to reduce wear or if knob feels gritty when turning. But remember, oil attracts dirt, so use it sparingly and keep your sight clean. **DO NOT** use oil on any other moving parts of the sight.
- We use spiralock® taps that resist bolt loosening. We recommend that you **DO NOT** use Loc-Tite on any sight parts.

With proper care and maintenance, your SURE-LOC® will give you many years of shooting enjoyment.